

VORSICHT!

Nicht springen

ATTENTION!

Do not jump

POZOR!



Neskákat











POZOR!

Neskákat'


UWAGA!

Nie skakać




 A x16 3,5 x 16mm	 B x24 4,0 x 35mm	 C x04
 D x04 1/4 x 70mm	 E x08 Ø10 x 40mm	 F x04
 G x01	H x02 82mm 	I x04 
		J x02 




01




2x



02



2x



03


C x02



D x02
1/4 x 70mm



G x01



04


C x02



D x02
1/4 x 70mm



G x01





05



B x22
4,0 x 35mm



H x02
82mm



06


I x04



B x02
4,0 x 35mm



J x02



VORSICHT!

Nicht springen

ATTENTION!

Do not jump

POZOR!

Neskákat

POZOR!

Neskákat'

UWAGA!

Nie skakać